



Inspection Detail

Click to watch the video



Client:	HDD Broker		
Inspected by:			
Location of Inspection:			
Phone No / Email:			
Date of Inspection:	11/6/2025	Job#:	
Year:	2017	Make:	Vermeer
Model:	D23X30III	VIN/SN:	

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Inspection Details

Unit Information

Hours:	3,527	Date:	N/A
--------	-------	-------	-----

General Body

Paint condition:	See Notes	Panel dents:	Yes	Corrosion:	No
Dents/Bends:	Yes	Visible leaks:	Yes	Operator console pivot/lock:	No Damages Observed
Operator's Seat:	No Damages Observed	Operator Console Joysticks, switches, gauges:	See Notes	Fresh water tank (if applicable):	See Notes

Safety Equipment

Operator's presence switch (seat):	No Damages Observed	Safety switches:	No Damages Observed	Red safety bars (rod loader extensions):	N/A
Work lights:	No Damages Observed	Strike alert/ground wire:	No Damages Observed	Safety decals:	No Damages Observed

Breakout System

Breakout jaw wear:	No Damages Observed	Cylinder and hose condition:	No Damages Observed	Pins/bushings slop:	No Damages Observed
Front Stakedown System:	See Notes	Auger condition:	See Notes		

Main Drive System

Tracks (steel or rubber):	Rubber	Track condition:	See Notes	Sprockets/rollers:	No Damages Observed
---------------------------	--------	------------------	-----------	--------------------	---------------------

Rear Outriggers

Cylinder and hose condition:	No Damages Observed	Pins and bushings:	No Damages Observed	Bent/broken parts:	Yes
------------------------------	---------------------	--------------------	---------------------	--------------------	-----

Carriage

Wear pads/carriage slop:	No Damages Observed	Motors and hoses condition:	See Notes	Rack and pinion condition:	No Damages Observed
--------------------------	---------------------	-----------------------------	-----------	----------------------------	---------------------

Engine Details

Fluid level and condition:		Visible leaks:	No	Belts and pulleys:	No Damages Observed
Engine mounts:	No Damages Observed	Radiator/hoses:	No Damages Observed		

Operation

Engine start and idle:	Yes	Engine smoke:	No	Engine noises (tick/knock):	No
Rear outrigger operation:	No Damages Observed	Main rack tilt:	No Damages Observed	Front stakedown rotation/up/down:	No Damages Observed
Breakout vices open/close/rotate:	No Damages Observed	Rod loader lift/shuttle/alignment:	No Damages Observed	Carriage traverse (thrust/pullback):	No Damages Observed
Rotation motor fwd/reverse:	No Damages Observed	Mud pump on/off:	No Damages Observed		

Drill Rods

Rod count:	40	Bent rods:	No	Thread condition:	No Damages Observed
Corrosion:	No				

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.

Tracks					
Left Track Condition:	See Notes	Left Tire Brand:	Obstructed	Left Tire Size:	Obstructed
LeftTrack Tread Depth Measurement:	16/32"	Left Track Rollers:	No Damages Observed		
Right Track Condition:	See Notes	Right Tire Brand:	Obstructed	Right Tire Size:	Obstructed
RightTrack Tread Depth Measurement:	16/32"	Right Track Rollers:	No Damages Observed		
Observations / Comments					
The unit starts and operates.					

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.



Wear and Tear Items

Item Name	Item Comments
Right Track	The track is worn, gouged and cracked.
Left Track	The track is worn, gouged and cracked.
Air Filter Housing Reducer	The air filter housing reducer is missing.
Tank Cap	The white tank cap is missing.
Iron Handle	The front iron handle near the bucket is bent.
Stake Down Weld	The stake-down yellow cylinder part has an aftermarket weld.
Stake Down Bolt	The bolt is missing on the bottom right base.
Rod Storage Frame	The frame is dented and scratched.
Engine Compartment Seal	The seal is damaged.
Hydraulic Elbow Fitting	The hydraulic elbow at the rear bottom, near the rear controls, is rusted.
Front Undercarriage	The front undercarriage is worn and has small dents.
Wet Hydraulic Hoses	A hydraulic hose is wet below the rod compartment.
Operator's Floorboard	The floorboard is cracking on the edge.
Monitor	The monitor panel is scratched and faded.
Operator's Controls	The controls are stained and dirty.
Right Joystick	The joystick screw is missing and the mini lever boot is torn.
Cup Holder Missing	The cup holder is missing.
Rivet Missing	The rear control panel has a missing rivet.
Rear Controls Frame	The rear control panel is dented.
Hydraulic Compartment	The hydraulic compartment has dents and scratches. Inside, a metal sheet on the left side is bent.
Engine Compartment	The engine compartment has dents and scratches.
Rod Back Panel	The back panel is dented and scratched.
Paint	The paint is damaged in several areas.

Disclaimer

Aspen is committed to providing helpful inspection reports to you. Aspen does not provide a warranty as to the information in the report. Furthermore, because Aspen does not at any time possess the property inspected, Aspen does warrant that the property inspected has not changed in a manner that would materially affect the inspection report.